



*We provide you with excellent documentation of the work we do.....*

**1976 MGB - Example Labor Operations ...**  
**(Taken from a customer's repair order)**

**Labor Operation # 72:** Recheck operation of heat control/valve/report- works ok now

**Labor Operation # 73:** Check air distribution control and mechanism operation

- A.) Air only to right side floor and right side defroster vent: no selection
- B.) Air control cable doesn't seem to be the correct one
- C.) Air distribution flap seized- needs heater box removal to correct problem
- D.) Nest debris in air box/ducts contamination
- E.) Fresh air door assembly seized

**Labor Operation #74:** Replace air distribution cable

**Labor Operation # 75:** Free up seized fresh air door. Let soak with penetrating oil, will not loosen up, door removal required

**Labor Operation # 76:** Remove fresh air door/free up/reinstall  
Right side hinge severely seized

**Labor Operation # 77:** Repair weld broken fresh air door hinge/free up/lube/reinstall.  
Both hinges work ok now.

**Labor Operation # 78:** Lube fresh air door positioning spring roller

**Labor Operation # 79:** Remove heat box

**Labor Operation # 80:** Clean nesting debris from heat box/air ducts

**Labor Operation # 81:** Clean heater core passages

**Labor Operation # 82:** Replace deteriorated heat box to body seals

**Labor Operation # 83:** Replace all deteriorated air distribution flap seals

***(Total labor operations: 92)***