

1971 Volkswagon Super Beetle

33,700 Miles – Very Clean – Not Rusted – Drives Like A New Car



RECENT HISTORY @ 33,700:

- Front Brake Cylinders (2)
- Front Brake Hoses (2)
- Clean, Lube & Adjust Front Brakes (10% Worn)
- Rear Brake Cylinders (2)
- Rear Brake Hoses (2)
- Clean, Lube & Adjust Rear Brakes (10% Worn)
- Left Inner/Outer Tie Rod Ends
- Oil Change – All Fluids Checked
- Right Inner/Outer Tie Rod Ends
- Lower Control Arm Bushings (Urethane)
- Sway Bar Thru Arm Bushings (Urethane)
- Sway Bar Mount Bushings
- Steering Damper and Bushings
- Alignment
- Great Heat
- Fully serviced

Additional Photos & Video @ www.CardoneandDaughter.com/sales

Cardone & Daughter Automotive, Inc.

4 CUSTOM DRIVE OLD SAYBROOK, CT 06475 PHONE: (860) 664-0727